

# Project 16458EZ: Veneer Bracelets



These lovely bracelets require little time or materials – two features that many woodworkers look for when selecting a project. The also make ideal gifts for friends and relatives, or to sell at gift shops and craft fairs.





## **Veneer Bracelets Step-by-Step Instructions**

### Step 1: Purchase Veneer and Inlay Banding

- 1. Purchase enough 1/32" thick veneer to make each bracelet desired. **NOTE: When selecting veneer, it's best to stick with a stock that's straightgrained. Burl and crotch stock are likely to split when bent, so avoid them.**
- 2. Purchase inlay banding for bracelets that you would prefer to have this replace the outer strip of veneer.

#### **Step 2: Make the Bracelet Form**

- 1. Face-glue two pieces of 3/4" thick by 3-1/2" square pine.
- 2. Scribe the appropriate profile from the full-size pattern. NOTE: **The profiles shown serve only as a guide, so you may want to make yours bigger or smaller.** Use a band or saber saw to cut out the profile.
- 3. Sand the profile smooth.

#### Step 3: Make the Bracelet

- 1. Select a suitable piece or suitable pieces of veneer for each bracelet.
- 2. Use a veneer saw or sharp razor knife to cut each piece (with the grain running lengthwise) to the desired width. **NOTE: Be sure the veneer doesn't overlap when bent around the form.**
- 3. Bring a pan of water to a boil.
- 4. Remove the water from the heat.
- 5. Soak the strips in the hot water until pliable (5-10 minutes). **NOTE: DO NOT** soak the inlay strips for more than 5 minutes or the small pieces may begin to separate.
- 6. Remove the strips from the water.
- 7. Wrap the strips around the form.
- 8. Secure the strips in place with a web clamp or masking tape
- 9. Allow the strips to dry overnight.
- 10. Remove the strips from the form and apply glue. Be sure to cover the surfaces thoroughly.
- 11. Apply a coat of paste wax to the form to keep the veneer from adhering to the form.
- 12. Reassemble the strips and secure with the web clamp or masking tape.
- 13. Allow to dry at least two hours.
- 14. Use sandpaper to sand all surfaces smooth, particularly the edges and the ends.
- 15. Apply Deft's clear semi-gloss interior finish for an attractive final finish. Dip the bracelets into the finish by fastening string to them with thumbtacks.

These plans were originally published in Volume 8, Issue 1 of *The Woodworker's Journal* (Jan./Feb. 1984, pages 46-47).